



GENERAL ELECTRIC COMPANY ..... 112 ANDOVER PARK EAST  
P. O. BOX 88850, SEATTLE, WASHINGTON 98188, Phone (206) 575-2864

INSTALLATION & SERVICE  
ENGINEERING DIVISION

ELECTRICAL & ELECTRONIC  
SERVICE DEPARTMENT

January 22, 1980

Lone Star Industries, Inc.  
3801 East Marginal Way South  
Seattle, Washington

Attention: Paul Burton

Gentlemen:

The following are the results of laboratory tests for P.C.B. concentration on twenty five oil samples:

S/N	LOCATION	TOTAL VOLUME	TEST RESULTS	PCB CLASSIF.
1 D-934201	Precip. Sec 2	155 gal	Less than 50 ppm	Non-PCB
2 7346603	Precip. 4 & 5	89	Less than 50 ppm	Non-PCB
3 2-44583	Incoming Trans	1456	Less than 50 ppm	Non-PCB
4 F-96331	Swg. Room <i>2 Silos</i>	135	Greater than 50%	P.C.B.
5 F-963295A	F.M. No. 1	180	Greater than 50%	P.C.B.
6 F-963295B	F.M. No. 2	180	Greater than 50%	P.C.B.
7 1605734	Old Silo South	30	Less than 50 ppm	Non-PCB
8 R-8078	Old Silo -	93	Less than 50 ppm	Non-PCB
9 SER-R-8078	Old Silo	93	Less than 50 ppm	Non-PCB
10 F-963294	Bottom <i>in</i> Silo	140	Greater than 50%	P.C.B.
11 1604543	Old Silo North	19	Less than 50 ppm	Non-PCB
12 1607627	Old Silo North	19	Less than 50 ppm	Non-PCB
13 1604538	Old Silo South	31	Less than 50 ppm	Non-PCB
14 1605735	Old Silo South	30	Less than 50 ppm	Non-PCB
15 0934203	Precip. North	155	Less than 50 ppm	Non-PCB
16 1529924	Raw Mill Tran. Rm.	154	Less than 50 ppm	Non-PCB
17 1529926	Raw Mill Tran. Rm.	154	Less than 50 ppm	Non-PCB
18 1608402	Old Silo North	19	Less than 50 ppm	Non-PCB
19 D-934202	Precip. Sec 3	155	Less than 50 ppm	Non-PCB
20 RHF-0282	Coal System	240	Less than 50 ppm	Non-PCB
21 No Number	Precip. 6		Less than 50 ppm	Non-PCB
22 PCR-61541	Slurry Tank <i>removed 3/14/89</i>	981	180 ppm	PCB-Contam.
23 E-686606	Hammer Head		Less than 50 ppm	Non-PCB
24 1529971	Raw Mill Tran. Rm.	154	Less than 50 ppm	Non-PCB
25 R-8078	Old Silo	93	Less than 50 ppm	Non-PCB

USEPA SF



1261023

AGC2F000121



Lone Star Industries, Inc.

-2-

January 22, 1980

From the results of these tests the following transformers have to be labeled as containing P.C.B.:

F-963361  
F-963295A  
F-963295B  
F-963294

Switchgear Room GRD Silos  
F.M. No. 1  
F.M. No. 2  
Bottom of Cin Silo

Find enclosed four PC-4 and PC-6 labels for this purpose. Use the largest label that can be applied to the transformer without folding. Apply these labels to an area of the transformer that is visible. You will also have to generate a P.C.B. equipment log listing each of these transformers by serial number, location, total gallons of P.C.B., date and classification of P.C.B. filled.

Transformer PCR-61541 slurry tank will also have to be entered in this P.C.B. equipment log and classified as P.C.B.-contaminated. It is not necessary or desirable to label this transformer since it is classified as P.C.B. contaminated not P.C.B. filled. This report should also be part of your P.C.B. equipment log as it is proof of the testing of your transformers insulating fluid and P.C.B. classification of these transformers.

If you have any questions regarding these test results or classification please contact me and reference our job number 438E4342.

Respectfully,

M. E. Elke  
Senior Field Eng. Pow. Del.  
ELEC. & ELECTRONIC DEPT.

MEE/ef

Encl.

AGC2F000122